




01 SP ø10x0,8 - d Vv

SP ø10x0,8 - 2,5 V10




02 SP 10x10x0,8 - d Vv

SP 10x10x0,8 - 2,5 V10




03 SP ø12x0,8 - d Vv

SP ø12x0,8 - 2,5 V10




04 SP ø10x0,8 - d Vv

SP ø10x0,8 - 2,5 V7




05 SPTD ø10x0,8 - d Vv

SPTD ø10x0,8 - 2,5 V7




06 SP ø15x0,8 - d Vv

SP 15x15x0,8 - 2,8 V15




07 SP ø20x0,8 - d Vv

SP ø20x0,8 - 2,8 V14 nedžerovaná




08 SP ø20x0,8 - d Vv

SP ø20x0,8 - 2,8 V14




09 SPTD ø20x0,8 - d Vv

SPTD ø20x0,8 - 2,8 V14




10 SPTD ø15x0,8 - d Vv

SPTD ø15x0,8 - 2,8 V10




11 SP ø20x20x0,8 - d Vv

SP 20x20x0,8 - 2,8 V20




12 SP cxc/øx10x0,8 - d Vv

SP 20x20/25x25x1,0 - 5 V20




13 SP ø25x25x1,0 - d Vv

SP 25x25x1,0 - 5 V20




14 SPTD ø25x25x1,0 - d Vv

SPTD 25x25x1,0 - 5 V30




15 SPTD ø25x25x1,0 - d Vv

SPTD 25x25x1,0 - 8 V20




16 SP ø30x30x1,0 - d Vv

SP 30x30x1,0 - 5 V28




17 SP 30x30x1,0 - d Vv

SP 30x30x1,0 - 8 V28




18 SP ø40x40x1,0 - d Vv

SP 40x40x1,0 - 8 V30




19 SP ø50x50x1,5 - d Vv

SP 50x50x1,5 - 10 V38




20 SP ø25x1,0 - d Vv


SP ø25x1,0 - 4 V18




PD 25x25x1,0




PD 40x40x1,0




PD 50x25x1,0




PD 80x40x1,0




SPTD ø25x1,0 - 4 V18




SP 50x25x1,0 - 5 V20




SP 50x25/65x25x1,0 - 5 V20




SP 60x30x1,0 - 5 V28




SP 60x30x1,0 - 8 V28




SP ø20x0,8 - 2,8 V14




SP 50x25x1,0 - 8 V20




SP 50x25x1,0 - 8 V20Z




SPTD 60x30x1,0 - 8 V28




SPTD 60x30/75x30x1,0 - 8 V28




SPTD ø20x0,8 - 2,8 V14




SPTD 50x25x1,0 - 8 V20




SPTD 50x25/65x25x1,0 - 8 V20




SPTD 50x25/65x25x1,0 - 8




SPTD 50x25x1,0 - 8 V20




SPTD 50x25x1,0 - 8 V20 - αtyp




SP 80x40x1,0 - 8 V30




SP 70x40x1,0 - 8 V30




SP 80x40/70x40x1,0 - 8 V30




SP 80x40x2,0 - 12 V30Z




SP3TD 50x25/65x25x1,0 - 8,0 V25 - atyp




SPTD 80x40x1,5 - 10 V30




SPTD 80x40/95x40x1,5 - 10 V30




SP 20x20x1,0 - 5 V20




SPTD 15x15x0,8 - 2,8 V15 HR30




SP 60x60x1,5 - 22 V50




SP 25x25x1,0 - 5 V20 HR30




SPTD 25x25x1,0 - 5 V30 HR30




SPTD $a \times 20 \times 0,8 - 2,8 \ V14 \ HR30$




SPTD 15x15x0,8 - 2,8 V15




SP 50x25x1,0 - 5 V20 HR30




SP 10x5x0,5 - V7




SPTD 20x20x1,0 - 5 V20 HR30




SPTD 20x20x1,0 - 5 V20




SP CH $\emptyset 14 \times V20 / HR \ 3,0 \times 40$




SP CH $\emptyset 14 \times 20 \ L65$




SP 20x20Lx0,8 - 2,8 V20




SP 30x30x1,0 - 8 V28 HR30




SPTD 25x25x1,0 - 8 V20 HR30




SPTD $\varnothing 10 / \varnothing 15 \times 0,8 - 2,8 \ V \ 10$




SP $\varnothing 15 \times 0,8 - 2,8 \ V10$




SPTD 50x25x1,0 - 5 V20




SPTD 50x25/65x25x1,0 - 5 V20




SPTD $\varnothing 25 \times 1,0 - 4 \ V18 \ HR30$




SP 20x15x0,5 - V 6,5




SPA $\varnothing 10 \times 0,8 - 2,5 \ V7$ SPB $\varnothing 10 \times 0,8 - 2,5 \ V7$




SP AL 20x20x1,0 - 5 V20




SP AL 20x20/25x25x1,0 - 5 V20




SP AL 25x25x1,0 - 5 V20




SP AL 30x30x1,0 - 5 V28




SPTD $\varnothing 10 / \varnothing 20 \times 0,8 - 2,8 \ V \ 10$




SP AL 50x25x1,0 - 5 V20




SP AL 60x30x1,0 - 5 V28




SP $\varnothing 20 \times 0,8 - 2,8 \ V14 \ HR30$




SPTD 50x25x1,0 - 8 V20 HR30




SPTD $\varnothing 10 \times 0,8 - 2,5 \ V6$




PD 100x25x1,0




SPTD 30x30x1,0 - 8 V28




SPTD 40x40x1,5 - 10 V30




SPTD 50x50x1,5 - 10 V38




SP $\emptyset 15 \times 0,8 - 2,8 \ V10 \ HRI30$




SP 50x25/65x25x1,0 - 8 V20




SP 65x25x1,0 - 5 V20



SP $\emptyset 20 \times 0,5 - 2,8 \ V14 \ HRI30$



SP 30x15x0,8 - 2,8 V12



SP $\emptyset 20 / \emptyset 25 \times 1,0 - 5 \ V \ 18$